



# Parker Street Waste Site Public Information Plan (PIP) Meeting

Thursday - January 29, 2009





## Agenda

- ☐ Investigation/Clean-up Status Report
- □ Walsh Field
  - Soil Contamination Overview & Arsenic Issue
- □ New Bedford High School (NBHS)
  - Soil/Groundwater & Interior PCB Source/Sink Issues
- ☐ Keith Middle School (KMS)
  - Long-Term Monitoring & Sediment Contamination Issue
- Public Involvement
  - Outline of future approach



## Investigation/Clean-up Status Report








## **Parker Street Waste Site Footprint**






## Walsh Field Sub-Areas of Site





## High School Campus Sub-Area of Site






## High School Interior Investigation/Remediation






## **KMS Wetland and Residences**





Sample/Boring Coverage — Site Wide





## Overall Investigation/Cleanup Status Summary

Location	Work Completed		In process
Walsh	<ul> <li>Varsity /JV IRA (field)</li> <li>IH controlled</li> <li>Environmental investigation</li> </ul>	<ul><li>Design basis memo</li><li>Current risk screening</li><li>Excavation analysis</li></ul>	■ Remedial planning
NBHS (exterior)	<ul><li>Environmental investigation</li></ul>	<ul><li>Current risk screening</li><li>Design basis memo</li></ul>	<ul><li>Excavation analysis.</li><li>Remedial planning</li></ul>
NBHS (interior)	<ul><li>Vent remediation</li><li>Source/sink sampling</li></ul>	<ul><li>Quasi-random sampling</li></ul>	<ul><li>Data analysis</li><li>Report prep.</li></ul>
KMS Wetland	<ul><li>IRA initiated</li></ul>	<ul><li>Environmental investigation ongoing</li></ul>	<ul><li>IH mitigation</li><li>Completion report.</li><li>Causal investigation</li></ul>
Residential (city)	■ Environmental investigation (a few remaining areas).		<ul> <li>Acquiring access to remaining areas.</li> </ul>
Residential (private)	■ Environmental investigation (a few remaining areas).		<ul> <li>Acquiring access to remaining areas.</li> </ul>



## Walsh Field Sub-Area





## Walsh Field — Background

## Findings from Environmental Investigation







#### ■ Environmental Investigation

- Soil analysis
  - Polyaromatic hydrocarbons (PAHs)
  - Polychlorinated biphenyls (PCBs)
  - Metals
- Supplemental arsenic analysis for baseball diamonds
- ☐ Findings
  - Primarily PAH and metals
  - Non-detect (ND)/low-concentration PCBs
  - Localized elevated arsenic in shallow soil on baseball diamonds




# Walsh Field — Overview Immediate Response Action (IRA)



- ☐ Varsity and Jr. Varsity Fields
  - Elevated arsenic soil concentrations
  - Triggered potential Imminent Hazard (IH) reporting and evaluation.
  - Other areas O.K.
- ☐ Findings
  - IH condition at Varsity Field
  - No IH at JV Field
- ☐ Immediate Response Action (IRA)
  - > RTN 4-21407



# Walsh Field Varsity & JV Diamond Soil Removal





# Walsh Field — Calendar of Events Varsity and JV Field Arsenic Contamination






- Reported to MassDEP (2-hour)
  - ➤ July 30<sup>th</sup>
- ☐ Supplemental soil sampling/risk analysis
  - > August 2008
- ☐ Filed IRA\* plan & Spec. Waste Determ.
  - November 2008
- Regulatory approval of IRA
  - November 2008
- Mayor directed additional removal
  - November 2008
- MassDEP approved Mayor's request
  - November 2008
- Soil removal and additional sampling
  - November 2008

## Walsh Field — Ensuring Safety/Managing Risk

## **©**TRC

#### **Varsity and JV Field Arsenic Contamination**




- □ Access restricted
- □ Arsenic surface soil removed
- □ Dust suppression/monitoring
- ☐ On-going risk evaluation
- ☐ Achieved significant risk reduction
  - Mitigated IH at Varsity
  - Further reduced risk at JV

## Walsh Field — Dust Monitoring



#### **Varsity and JV Field Arsenic Contamination**



- Real-time field instrumentation and back-up laboratory analysis
- □ No dust levels in excess of action levels.
- □ All arsenic air results non-detect \*

<sup>\* -</sup> Detection limits set below concentrations of concern for human health.

## Walsh Field — Next Steps




#### **Varsity and JV Field Arsenic Contamination**



- ☐ Dispose of soil stockpile
- ☐ Design comprehensive remedy for entire field
  - > Arsenic and lead driven
- ☐ Implement long-term solution




## High School Campus Sub-Area



#### Soil and Groundwater Data Collection

**Exterior Soil and Groundwater** 





## □ Preliminary Findings

- Generally consistent with past work by BETA
- Groundwater data also collected
- ☐ Athletic Fields/Grounds
  - Precautionary surface soil data collection following Walsh Arsenic discovery
  - No exposures of concern detected in shallow soil (0 -1 foot below grade).

## **©**TRC

Soil and Groundwater Data Collection
Sub-Slab Soil and Groundwater




## □ Soil Analysis Findings

- 8 sub-slab soil borings
- Low concentration PCBs
- Sporadic metals above standards
- One PAH detect above standard [benzo(a)pyrene].
- ☐ Groundwater Findings
  - > 3 sub-slab wells/2 exterior wells
  - Exceedance in one well due to turbidity (boiler room)
  - > Filtered result OK


## **©**TRC

Soil and Groundwater Data Collection Investigation Locations





## High School Interior









## NBHS Interior (Source/Sink Investigation)

## **Recent Accomplishments**





- Remediation Initiated
  - ➤ July 2007
- □ Remediation Completed
  - > August 2007
- ☐ HVAC Repairs/Balancing
  - ➤ February 2008
- □ PCB Air Sampling
  - ▶ February 2008



## **NBHS** Interior

#### **Notes on Process**

Response	Status
Visual Inspection (sources)	Done
Re-sampling	Done
Verbal Report to City	Done
Interviews with personnel	Done
Consultation with laboratory	Done
Supplemental Assessment Plan	Completed July 2008
Quasi-Random/Substrate Sampling	Completed December 2008



## **Scope and Accomplishments**





## Completed July 2008

- √ Visual assessment/materials quantification
- ✓ Sample additional materials
- ✓ Further evaluation of concentration trend
- √ 63 bulk samples, 8 wipe samples

## Completed December 2008

- ✓ Quasi-random sampling plan
- √ 218 bulk/wipe samples
- √ 10 depth samples



#### **Findings**



Laminate Adhesive

- ☐ Additional PCB-containing building materials (e.g., adhesives, gaskets)
- □ Numerous low-concentration building materials serve as sources of indoor air PCBs
- □ Higher PCB air concentrations trend with higher aggregate PCB building material concentrations



Findings (continued)

- ☐ July 2008 Bulk Building Material PCB Results
  - > PCBs detected in 57 out of 63 building material samples
  - Concentration range: 0.16 ppm to 230 ppm (Total PCBs)

- ☐ July 2008 PCB Wipe Sampling Results
  - PCBs detected in 5 out of 8 wipe samples
  - > Results range: 1.5 ug/100 cm<sup>2</sup> to 7.1 ug/100 cm<sup>2</sup>



## **NBHS** Interior - Possible Data Trend

## 2007/2008 Bulk and Air Results

Medium	B-240	A-114-3	High Conc. Correlation	
Floor Tile Mastic	10.1 ppm	0.2 ppm	B-240	C
Window Glazing	14.9 ppm	2.1 ppm	B-240	U
Baseboard Mastic	4.5 ppm	2.0 ppm	B-240	n
Old Paint	0.2 ppm	8.3 ppm		U
Recent Paint	2.9 ppm	1.6 ppm	B-240	
Steel Beam Paint	6.4 ppm	4.3 ppm	B-240	
Vinyl Cove Base	7.8 ppm	3.7 ppm	B-240	
Vinyl Floor Tile	2.6 ppm	0.18 ppm	B-240	
Floor Tile Mastic	10 ppm	0.69 ppm	B-240	
Push-pin Board	7.5 ppm	2.97 ppm	B-240	
Laminate Adhesive	230 ppm	1.31 ppm	B-240	
Air Result 2007	0.32/0.044 ug/m <sup>3</sup>	0.08/0.040 ug/m <sup>3</sup>	B-240	

Concentration Units:

Bulk results in mg/Kg (ppm) Air Results in ug/m3




Findings (continued)

- ☐ December 2008 Quasi-Random PCB Results
  - PCBs detected in 207 of 218 building material samples
  - Concentration range: 0.05 ppm to 176.9 ppm (Total PCBs)

- □ December 2008 PCB Depth Sampling Results
  - PCB depth sampling results pending



Source/Sink Sampling





#### **NBHS** Interior

#### **Next Steps Lead up to Remediation**





- ☐ Remedial Planning/Specification Prep.
  - Initiate during Winter 2008/2009
  - Solicit bids Spring/Summer 2009
  - Initiate remedy when practicable
- ☐ Targeted Pre-/Post-PCB Air Monitoring
  - Bracket remedial effort



# Keith Middle School Monitoring and Wetland Sediment Contamination





#### **Keith Middle School**

#### **Long-Term Monitoring Program**





- ☐ Scope and Accomplishments (2008)
  - Groundwater Monitoring Done.
  - Cap Inspection Done.
  - Wetland Inspection Done.
  - Sediment Monitoring Ongoing Evaluation.
  - Annual Update Training Done.
  - KMS Indoor Air & Vent Sampling Done.



#### **Keith Middle School**

#### **Groundwater Monitoring**

- ☐ Analysis of Samples from 3 Wells
  - Volatile Organic Compounds (VOCs)
  - Polychlorinated Biphenyls (PCBs)
  - Metals
- □ Results
  - VOCs: All non-detect (except MTBE, below standards)
  - > PCBs: All non-detect
  - > Metals: No detections above standards



## **Keith Middle School**

## **Groundwater Monitoring Well Locations**





#### **Cap Inspection - LTMMIP**

#### KMS Front Entrance (View South)



- □ Conducted Three Times/Year
- □ Inspection Scope
  - Walking traverse of entire site
  - Visual observations of entire cap
    - First floor concrete slab
    - Interior courtyard
    - All asphalt and landscaped surfaces



#### Cap Inspection (continued)

# KMS North Wetland (View North)



#### ☐ Inspection Findings

- Concrete slab in acceptable condition
- Exterior pavement and concrete surfaces in acceptable condition
- Courtyard surfaces in acceptable condition
- Exterior landscaped areas are acceptable except as follows:
  - Sparse vegetation southern slope
  - Area of slope failure (recently repaired).
  - Sloughing rip-rap west side/storm drain
  - Minor erosion northwest corner




**Cap Inspection (continued)** 





#### **Wetland Inspection - LTMMIP**

#### KMS North Wetland (View South)



- ☐ Conducted in Spring 2008
- ☐ Inspection Scope
  - Walking traverse of top & toe of slope
  - Look for unacceptable conditions:
    - Excessive sedimentation
    - Conditions that could cause excessive sedimentation
    - Vegetation conditions



#### Wetland Inspection (continued)

- □ Wetland Inspection Findings
  - Generally well vegetated slope
    - > Exploring vegetation/animal control options
  - Similar erosion issues as noted in cap inspection
  - ➤ Temporary repair still viable with some localized soil migration around the lower hay bales (permanent repair implemented since time of inspection).




**Wetland Inspection (continued)** 





#### Wetland Sediment Sampling/Monitoring - LTMMIP



- □ Long-Term Monitoring and Maintenance Implementation Plan (LTMMIP)
- ☐ Sampled Spring 2008
- Monitoring scope
  - Four randomly collected sediment samples (base of slope)
  - Analyze samples for PCB Aroclors (Method 8082)




#### Wetland Sediment Monitoring (continued)

#### ☐ Monitoring Findings

- > Three out of four samples non-detect
- ➤ One sample detected PCBs (16.6 mg/kg)
- Triggered potential Imminent Hazard reporting and evaluation under the MCP (reported to MassDEP)
- ➤ Preliminary calculations indicate an Imminent Hazard exists (TRC's calculations slightly exceed the Imminent Hazard criteria set forth in the MCP under 310 CMR 40.0955)
- > Delineation and evaluation ongoing



#### **Wetland Sediment Monitoring (continued)**





#### **Annual Update Training**

- ☐ KMS Remedy Related Worker Training
  - > Location of impacted soil at the site
  - ➤ Purpose of the AUL
  - Work allowed under the AUL
  - > When to contact the LSP
  - Required Inspections
  - Summary of monitoring findings
- ☐ Performed by City in April 2008



#### **Indoor Air & Vent Monitoring Update**

- ☐ TRC Monitoring since March 2007
- □ PCBs Indoor Air/Vents
- □ VOCs Indoor Air/Vents





# KMS Air Monitoring PCBs

□PCBs KMS indoor air equivalent or less than background air

□PCBs below EPA Action Level (0.05 ug/m3)

□ PCBs Present in Vent Samples Periodically (Background)



#### Risk Evaluation for Indoor Air Keith Middle School

□Some compounds detected above AAL/TELs\*

□AAL/TELs are outdated

□Risk evaluation shows no risk above MassDEP criteria

□TRC has recommend and is using updated comparison criteria based on more current toxicology

\*AAL — Allowable Ambient Limit

TEL — Threshold Effect Exposure Limit



# **VOC Measurements Summary of Findings**Keith Middle School

- □ VOCs Present in Vents Consistently
- VOCs in Vents
  - > Generally decreasing in concentration over time
  - Also reflects compounds in soil gas (indicates system performing as designed)
- □ VOCs KMS Indoor Air
  - Background concentrations (off-gassing of building materials)
  - > Also attributable to maintenance activities



# Public Involvement Outline of Future Approach



#### **Public Involvement**


- ☐ Minimum of Quarterly Public Meetings
- ☐ Periodic Milestone Meetings
  - Outline of remedial approach
  - Issuance of major deliverables
- ☐ Massachusetts Contingency Plan Requirements
- ☐ On-line Posting of Data and Project Documents



# Investigation/Remediation Road Map



## **Summary Site Overview**





#### Overall Investigation/Cleanup Status Summary

Location	Future Work
Walsh	Initial phase remedial design in 2009
	<ul><li>Phased implementation 2009/2010</li></ul>
	As needed delineation
NBHS (ext)	■ Initial phase remedial design in 2009
	<ul><li>Phased implementation 2009/2010</li></ul>
	As needed delineation
NBHS (int)	■ Remedial planning (winter 2009)
	EPA planning documentation
	<ul><li>Specification prep (winter/spring 2009)</li></ul>
	■ Bid process (spring 2009)
	<ul><li>Initial phase remedy (summer 2009)</li></ul>



#### Overall Investigation/Cleanup Status Summary

Location	Future Work
KMS Wetland	<ul> <li>Initial phase remedial design in 2009</li> <li>Implementation 2010</li> <li>As needed delineation</li> </ul>
Residential (city)	<ul> <li>Wrap up investigation (2009)</li> <li>Pre-demo environmental sampling (2009)</li> <li>Demolition (spring 2009)</li> <li>Initiate remedial planning (2009)</li> <li>Initial phase remedial design in 2009</li> <li>Phased implementation 2009/2010</li> <li>As needed delineation</li> </ul>
Residential (private)	<ul><li>Wrap up investigation (2009)</li><li>Case-specific planning</li></ul>



# Thank You for Your Time and Attention

## **Questions are Welcome**